

## Message

**From:** Bury, Carolyn [/O=EXCHANGELABS/OU=EXCHANGE ADMINISTRATIVE GROUP (FYDIBOHF23SPDLT)/CN=RECIPIENTS/CN=DE91ECB9B8C044A4BF4C350615AE3633-CBURY]  
**Sent:** 11/12/2018 6:01:44 PM  
**To:** Brad Gentry [bgentry@iwmconsult.com]  
**CC:** Chris Parks [cparks@iwmconsult.com]; Sundar, Bhooma [sundar.bhooma@epa.gov]; Neal, Conor [Neal.Conor@epa.gov]; Joe Bianchi (jbian@amphenol-aao.com) [jbian@amphenol-aao.com]  
**Subject:** RE: Smoke/pressure test and Sewer Addendum to WP results?

Thanks, Brad.

We will review the data and schedule a discussion.

Would you please describe the Adams St neighborhood? Is that the area east of Forsythe and south of the Study Area?

Sorry that I didn't get around to scheduling a meeting for Friday last week. I will schedule one for this week. Is Wed afternoon good at your end?

Carolyn

---

**From:** Brad Gentry <bgentry@iwmconsult.com>  
**Sent:** Monday, November 12, 2018 6:17 AM  
**To:** Bury, Carolyn <bury.carolyn@epa.gov>  
**Cc:** Chris Parks <cparks@iwmconsult.com>; Sundar, Bhooma <sundar.bhooma@epa.gov>; Neal, Conor <Neal.Conor@epa.gov>; Joe Bianchi (jbian@amphenol-aao.com) <jbian@amphenol-aao.com>  
**Subject:** RE: Smoke/pressure test and Sewer Addendum to WP results?

Carolyn

Attached are the draft results for the supplemental sewer gas sampling activities and map displaying the sampling locations. As you can see, the analytical data appears to be variable between sampling events and may be related to temporal variations or other factors. Also, please note that although the southernmost manhole (MH #240020) exhibited the highest VOC concentrations, there were numerous samples obtained further upstream (i.e. closer to the Former Amphenol site) from this manhole that were less than the applicable screening levels, which strongly suggests that the VOCs detected in MH #240020 are not associated with the Former Amphenol facility. I also know for sure that the city was conducting a sewer lining project in the Adams Street neighborhood at the time of the sampling so this may have affected the results of the sampling activities.

Please contact us with questions or if you need anything else.

Sincerely,

Bradley E. Gentry, LPG  
 Vice President/Brownfield Coordinator  
 IWM Consulting Group, LLC  
 7428 Rockville Road  
 Indianapolis, IN 46214  
 Mobile: (317) 435-8877  
 Office: (317) 968-9256  
 Fax: (317) 347-9326

---

**From:** Bury, Carolyn <bury.carolyn@epa.gov>  
**Sent:** Saturday, November 10, 2018 7:59 PM  
**To:** Brad Gentry <bgentry@iwmconsult.com>  
**Cc:** Chris Parks <cparks@iwmconsult.com>; Sundar, Bhooma <sundar.bhooma@epa.gov>; Neal, Conor

[<Neal.Conor@epa.gov>](mailto:Neal.Conor@epa.gov)

**Subject:** Smoke/pressure test and Sewer Addendum to WP results?

Hi –

Do you have any updates from the smoke tests and the additional five manhole investigations?

Thanks.

Carolyn

Carolyn Bury  
Corrective Action Project Manager  
Remediation and Re-use Branch  
Land and Chemicals Division  
U.S. Environmental Protection Agency  
77 W. Jackson Blvd. LU-16J  
Chicago, IL 60604

312-886-3020

[bury.carolyn@epa.gov](mailto:bury.carolyn@epa.gov)